

Less a
Eng
TONN.
Less 1
Less A

F.E.

Received by Chief Ship Surveyor 13. 10. 05

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Steam Trawler "Asia"* Rpt. Hull No. 17243

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>9/16" in lieu of 8/16"</i>	<i>not required</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary, 5/16" in lieu of 5/16" and spaced (viz., ordinary, deep, zed, channel or bulb-angle). 1" close stem required.</i>		

The 1st Anclm is 17 lbs. less in weight than required, but the 2nd. and 3rd. Anclms are 37 lbs. and 21 lbs. respectively in excess.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A 1 ("Steel") *Steam Trawler* as recommended.

∇ 100 A 1 ("Steel") *Steam Trawler*

1 DR.

BK 9" 4BH Am. Lloyd's A&CP Q60' F24'

C. H. J.
13/10/05

© 2021



Lloyd's Register Foundation
W971-0160

5c.5.5.

WEBI

WEBI