

COPY FOR LONDON OFFICE.
Lloyd's Register of Shipping.



Port ALEXANDRIA

3rd August 1917

This is to Certify that I have

Surveyed the ~~Boiler and Machinery~~ of the Parts of the Motors
and repairs done, as given on the other side of the British
twin screw steamer "ARABIS", 3928 tons gross, of London

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that this ~~examination~~ examination be noted as
part of the Annual Special Survey of the machinery of this vessel
be made in the Register Book in the case of this vessel.

Survey Fee £3 - 3 - 0

Expenses 6 - 0.

J. Roberts

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed it is to be understood
that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
certificate issued by the Society or its Surveyors, or in any entry in the Register Book or under publication of the Society, or for any error
of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



REGISTERED FOR LLOYD'S REGISTER OF SHIPPING

ALEXANDRIA Port



The 3rd Cylinder and piston, of Port Motor,
The original piston which had a fracture in the top, has been taken out and replaced by the spare piston.

The Crank shaft and main bearings of Starboard Motor.
All bottom halves of main bearings have been now remetalled, and shaft lined up to Lloyd's gauge. The holes in coupling, between fly-wheel and No 6 Bearing, rimmed, and new coupling-bolts fitted.

Remetalled No 4 Guide Shoe.

Signature and text: "Lloyd's Register of Shipping"

This certificate is issued upon the terms of the Rules and Regulations of the Society, which are published in the Register of Shipping, and it is to be understood that the Committee are under any circumstances liable to be held responsible for any inaccuracy in any report or other publication of the Society, or for any alteration in the Register of Shipping, or for any other cause.



Lloyd's Register Foundation

Damage or Repair Fee (per Section 25.)
Travelling Expenses (if char...

Tonnage Net
Registered Horse Power
No. of Main Boilers
Donkey Boilers
Main Boilers
Donkey Boilers
st Report
rticula
Medical Survey
e of Repair
unt of Dam
des being d
s and initia
mage case
colined?
e Surveyor p
was not dor
hat parts of
hat special m
eyor to assu
Surveyor ex
e Surveyor e
Surveyor ex
Surveyor ex
Surveyor ex
w shaft nov
now been
ft now fit
istance bet
y is not co
carnu
as fo
le sp
Cra
rains
The
good
No
eral Obser
to clearly what a
any alterati
140 lb., F.D.
The
Specia