

2E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Lanzam

Rpt.

Pd.

No.

2219

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 11/31 ~~partly~~ held at

sted, and the following repairs carried out (due to ~~Wear~~ *Wear*):-

Some electric cables renewed  
Minor repairs to Boilers.

It is submitted the vessel is eligible to remain as classed, with

on of

RS 136.

as recommended.

It is concluded that the new electric fittings are in accordance with the Rules but this should be confirmed.

*Ms. Sup. Said Lelli 30/3/36*



of 3/36

Lloyd's Register Foundation

W98-0115