

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 13<sup>th</sup> Nov 1918 When handed in at Local Office 13<sup>th</sup> Nov 1918 Port of Philadelphia Pa  
 No. in Survey held at Chester Pa Date, First Survey 30<sup>th</sup> Sept Last Survey 4<sup>th</sup> Oct 1918  
 Reg. Book. on the Wood, Iron or Steel S.S. "LA BREA" Master J. A. Grant

TONNAGE: Built at San Francisco By whom Union Iron Works When 1916 - 3  
 GROSS 6945 Owners Union Oil Co of California Port belonging to San Francisco  
 UNDER DK. C.H.H.3 Owners' Address \_\_\_\_\_  
 NET 4257 (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock San S.B.Co Destined Voyage Mexico  
 WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted  
 total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, beams, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 2707 Port S. Fo.

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned or when expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100A1 H17</u>	<u>4/18</u>	<u>+LMC 3,16</u>
<u>carrying Oil</u>		
<u>in Bulk</u>		
<u>With for oil fuel 3-16 F.P. at 100°F.</u>		
<u>Society's Freeboard (if assigned) as painted on Ship and now verified</u>		

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs due to other causes: account of Damage (the cause of which must be stated) should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Alterations

Work done: Seared Steam Turbine and seating for same completely removed. Tank top in Engine Room specially examined and new seating for Reciprocating Engines efficiently built in accordance with approved plan. Engine Room tank tested under water pressure and found satisfactory.  
Also done: Weather decks and General Equipment examined.  
The approved plan of Engine Seating is forwarded herewith.

STATE OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—																																																
Renewed																																																								
Removed and Faired or Repaired																																																								
Faired or Repaired in place																																																								
GENERAL CONDITION OF THE	<table border="0"> <tr> <td>Stringers <u>(Upper deck) Good</u></td> <td>Dblg. Plates under Sounding Pipes</td> <td>Copper or Y.M. of Wood Vessels</td> </tr> <tr> <td>Inner Bottom Plating <u>in Engine Room</u></td> <td>Engine Room Skylights <u>Good</u></td> <td>(State if on Vell.)</td> </tr> <tr> <td>State if Tanks have been examined inside</td> <td>Coal Bunker, Open'gs, Lids, &amp;c.</td> <td>When put on, Month</td> </tr> <tr> <td>State if Tanks now tested <u>in Engine Room</u></td> <td>Scuppers</td> <td>Boats</td> </tr> <tr> <td>Bulkheads</td> <td>Cargo Hatchways</td> <td>Masts, Yards, &amp;c.</td> </tr> <tr> <td>Ceiling</td> <td>Hatches</td> <td>Condition, how ascertained <u>From deck</u></td> </tr> <tr> <td>Cement or Asphalt</td> <td>Planking of Wood Vessels</td> <td>(state if wedges removed)</td> </tr> <tr> <td>Rudder</td> <td>Caulking</td> <td>Sails</td> </tr> <tr> <td>Steering gear and its connections <u>Good</u></td> <td>Treenails</td> <td>Equipment letter <u>64</u></td> </tr> <tr> <td>Windlass</td> <td>Breasthooks &amp; Stemson</td> <td>Anchors, No. of <u>3 B, 15, 115</u></td> </tr> <tr> <td>Have Pumps now been examined and found efficient?</td> <td>Transoms, Pointers, &amp; Crutches ditto</td> <td>Cables (State if now ranged)</td> </tr> <tr> <td>Have Sluice Valves now been examined and found efficient?</td> <td>Timbers of Frame at openings ditto</td> <td>length</td> </tr> <tr> <td>Have Watertight Doors now been examined and found efficient?</td> <td>Ditto ditto at other places ditto</td> <td>(on board) <u>Water complete</u></td> </tr> <tr> <td></td> <td>Stringers, Clamps &amp; Shelves ditto</td> <td>Rule length <u>Water complete</u></td> </tr> <tr> <td></td> <td>Salting (State if examined.) ditto</td> <td>Hawser &amp; Warps <u>Sufficient</u></td> </tr> <tr> <td></td> <td></td> <td>Standing &amp; Running Rigging <u>Good</u></td> </tr> </table>								Stringers <u>(Upper deck) Good</u>	Dblg. Plates under Sounding Pipes	Copper or Y.M. of Wood Vessels	Inner Bottom Plating <u>in Engine Room</u>	Engine Room Skylights <u>Good</u>	(State if on Vell.)	State if Tanks have been examined inside	Coal Bunker, Open'gs, Lids, &c.	When put on, Month	State if Tanks now tested <u>in Engine Room</u>	Scuppers	Boats	Bulkheads	Cargo Hatchways	Masts, Yards, &c.	Ceiling	Hatches	Condition, how ascertained <u>From deck</u>	Cement or Asphalt	Planking of Wood Vessels	(state if wedges removed)	Rudder	Caulking	Sails	Steering gear and its connections <u>Good</u>	Treenails	Equipment letter <u>64</u>	Windlass	Breasthooks & Stemson	Anchors, No. of <u>3 B, 15, 115</u>	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	(on board) <u>Water complete</u>		Stringers, Clamps & Shelves ditto	Rule length <u>Water complete</u>		Salting (State if examined.) ditto	Hawser & Warps <u>Sufficient</u>			Standing & Running Rigging <u>Good</u>
Stringers <u>(Upper deck) Good</u>	Dblg. Plates under Sounding Pipes	Copper or Y.M. of Wood Vessels																																																						
Inner Bottom Plating <u>in Engine Room</u>	Engine Room Skylights <u>Good</u>	(State if on Vell.)																																																						
State if Tanks have been examined inside	Coal Bunker, Open'gs, Lids, &c.	When put on, Month																																																						
State if Tanks now tested <u>in Engine Room</u>	Scuppers	Boats																																																						
Bulkheads	Cargo Hatchways	Masts, Yards, &c.																																																						
Ceiling	Hatches	Condition, how ascertained <u>From deck</u>																																																						
Cement or Asphalt	Planking of Wood Vessels	(state if wedges removed)																																																						
Rudder	Caulking	Sails																																																						
Steering gear and its connections <u>Good</u>	Treenails	Equipment letter <u>64</u>																																																						
Windlass	Breasthooks & Stemson	Anchors, No. of <u>3 B, 15, 115</u>																																																						
Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)																																																						
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length																																																						
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	(on board) <u>Water complete</u>																																																						
	Stringers, Clamps & Shelves ditto	Rule length <u>Water complete</u>																																																						
	Salting (State if examined.) ditto	Hawser & Warps <u>Sufficient</u>																																																						
		Standing & Running Rigging <u>Good</u>																																																						

### General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

As far as seen this vessel is in good and efficient condition and eligible in my opinion to remain as classed without fresh record of survey.

Fee (per Section 28)	£ 8 : 65 : 00	Fees applied for,
Damage or Repair Fee (if any)	£ :	19
Expenses (if chargeable)	£ 5 : 00	Received by me,
Surveyor's Fee (if any)	£ :	19

James Butler  
 Surveyor to Lloyd's Register of Shipping.

Committee's Minute New York DEC - 3 1918  
 Character Assigned As now without spl. and subd.  
+ N.E. 11.18 T.S. 11.18



COPY FOR Lloyd's Register



Is certificate required? If so, to be sent to...