

1

Labrad

Chief Surveyors 11.7.18

Received from Chief Surveyors

EL'S NAME

Sheells Ardgoon

Report

Lab

No. 17326

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

of Survey

When due

The Dornier pump & keel anchor have been dispensed with for the present & the Surveyors state the Owners are agreeable to fit these at the end of the War, if requested to do so.

A letter agreeing to the omission of the tween deck bulkhead (from Owners) is attached to the first entry report of the sister vessel "Ardgoon".

100A.1 (Steel)

2 Dks (Steel) & Webframes. Longitudinal Framing

Cell DTB a 129' w E 21' + 176' 10936. D.T. a 36' 9586. A.P.T. 39C

F.K. "tween Dk bulkhead in after hold dispensed with. 5 B.H. to

Upper Dk. 1 B.H. to 2" Dk only"

Rem. Legs axes. P36. B.120' F 44'


Carrying oil fuel FP above 150°F in double bottom & deep tanks

M 11.7.18

The Surveyors should be again requested to forward a sketch showing the details of construction in way of the fore peak.

Please pass report to Mr. Maynard

W982-0279



See letter 18 20.7.18 W.M.

Lloyd's Register Foundation

BEAMS, Second Deck, Single Angle, Double Angle, Plate, Tee Bulb, or Channel Spacing

Deck Material & thickness  
Poop Deck Stringer Plate, breadth & thickness