

a damage report made by anyone else? If so, by whom?
The Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Starboard

11 58 1940
5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "JACOBUS"

Rpt. Nwc.

No. 98379

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. -- Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~DAMAGE~~ WEAR AND TEAR.

The class is subject to some tubes in the starboard boiler being renewed before the end of 3.40.

These defective tubes have now been renewed.

It is submitted the vessel is eligible to remain as classed with record of Survey as recommended.

Without special condition.



© 2020

Lloyd's Register Foundation

10.4.40

Boilers now renewed!