

Residence

F.E.

Received from Chief Ship Surveyor

No. 32492

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

© 2020

W985-0077

W985-0077

35	Tie Plates.....	Founda
36	Deck. Material and thickness.....	
	Forecastle Deck Stringer Plate, b'dth & th'kns	
37	Angle on ditto.....	

$$15 \times 34 = 510$$

$$3 \times 2\frac{1}{2} \times \frac{5}{16} = \frac{15}{8}$$