

11 SEP 1940

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME "JOSEPH SWAN" Rpt. Nwc No. 98748

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


The NEWCASTLE Surveyors report the vessel placed in dry dock, the bottom coated, and on account of damage through enemy aerial action, 8 bow plates and the framing in way etc. repaired.

IT IS SUBMITTED the vessel appears worthy to remain as classed with record of survey 8.40.

100A1
8.40 Bly

Sunk - war loss

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 9.9.40

Lloyd's Register
Foundation