

Extends up to upper deck

bottom Angles double

100 90 14

n.9.22.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl T.S. M/V " BRALANTA Rpt. sun No. 8754


The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

This vessel has left Dundee for Gothenburg to have the machinery installed.

It is submitted the Gothenburg Surveyor be advised and requested to give the case the necessary attention and to forward a report on form 8 when the survey has been completed.



© 2020

Lloyd's Register
Foundation

W 986-0110

13.5.31

Flat Plate Keel Angles

fits internally

Spacing

GIRDER

side Keelsons No. each side one 12 1/2 x 4 x 625 BA