

King Robert.

126 JAN 1933
Led. 3/145.

It is intended that before this
case receives consideration the Ammiral
be requested to state whether the propeller
& sea connections were examined
as there are not mentioned in the report.
He should also state why the main
steam pipes were renewed as according
to the I.C. Report these were ~~still~~ originally
of steel.

Br Lth 21/6/1933

[Signature]

16/1/32.

© 2019

Lloyd's Register
Foundation