

LEITH

25th January 1928

EVAN EDWARDS

the Builders of the vessel, survey the ss. "WESTBURY" of London, with view to ascertaining the nature and extent of damage stated to have been sustained on 22nd. November 1927 through striking the dock wall while entering the Harbour at Leith with view to having her machinery and Boilers installed.

On 7th December 1927 and subsequent dates while lying on mud flat and afloat in the Harbour of Burntisland surveyed the vessel found and recommended as follows:-

FOUND.RECOMMENDED.STARBOARD SIDE.

The shell plating in way of the common landing of "G" and "H" strakes between frames No.21 & 22 from the collision bulkhead indented.

To be faired in place.

The above recommendations were made with view to placing the vessel in as good condition as before the time of the accident.

On the 12th January 1928 while lying afloat in the Harbour of Burntisland the vessel was surveyed and it was found that all repairs in connection with the damage in question have been satisfactorily carried out.



Evan Edwards
SURVEYOR TO LLOYD'S REGISTER

Lloyd's Register
Foundation

W 99 - 0025