



Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 26th April, 1939.



Dear Sir,

In reply to the enquiry contained in your classing letter of the 25th instant respecting the case of the Steam Trawler "KINGSTON CAIRNGORM" we have to state that no quill shaft is fitted on this vessel, the Bauer-Wach drive being direct to the shaft.

For your information we beg to state that no Bauer-Wach trawlers in this Port are fitted with quill shafts.


We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:- J. A. Ode

The Secretary,
LONDON.



© 2019

Lloyd's Register
Foundation

Insert in S.R.L. Structure in way of who sounding device to be further
when device is removed.

S.S. Lt. Held

Deferred to Mr. Ellis

Noted

27 APR 1933

*Noted
Gruen*

RECEIVED
LLOYD'S REGISTER
LONDON

© 2019

Lloyd's Register
Foundation

NAME

by Chief Ship S

Remarks of th

"The endorsement
to bring on
presented in

of Survey

image thro

repare

newed ...

removed and
or repair

ired or r
in place.

her items

The

Following

It is

It is

lowed to

S.S.

100 Al
Slin

The fo

z:-

Present in