

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME KOHINUR Report GLS No. 62960For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING When due.....

Subject to permanent repairs to an indented plate in
1st and in 2nd staves below sheer and framing
in way abreast No 1 hatch on port side and to
ventilator coamings being dealt with at the first
available opportunity.

was
19.10.40



© 2019

Lloyd's Register
Foundation