

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl S THE VICEROY Report Sl No. 49048**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due Revised Rules.


✠ 100 A. I. (Steel)

1 D¹⁰ (Stl) Well D¹⁰

Cell D.B. 123' 174t, F.P.T. 56t, A.P.T. 22t.

F.K, 3 B.H, Cem, Lloyds A CP.

Q 111', B 11', F 30'. machy aft


 A handwritten signature in dark ink, followed by the date "11.4.29." written in a cursive style.

It is concluded the thickness of the strake below the sheerstrake, the size of the bridge & fore Cas^{ts} deck stringer plates and ties as approved but the Surveyors should be requested to state if this is so.



© 2020
Lloyd's Register
Foundation