

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Rpt.

No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE TO ENGINES AND BOILERS.

This vessel is reported by the Surveyor to have sustained damage to through

Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to

The Surveyor recommends


It is submitted



© 2020

Lloyd's Register Foundation

The main engines were constructed in 1945 under the supervision of the Society's Surveyors, acting on behalf of the Ministry of Supply. They were not installed under Special Survey, but have now been examined & found to be fitted on board in accordance with the Rules. For examination now held see report 9.



© 2020

Lloyd's Register Foundation

Handwritten notes: 10 Oct, 2025, Mr. V.