

COPY.

21 JUL 1947

Lloyd's Register of Shipping.



Port SINGAPORE

14th June, 1947.

This is to Certify that I have

Surveyed the ~~Boiler and Machinery of the~~ repairs to the port
and centre boilers of the Steel Twin Screw Steamer "HONG KHENG",
6167 tons gross of SINGAPORE, whilst lying afloat at this
port,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that ~~the record of~~

no alteration

be made in the Register Book in the case of this vessel.

John Wormald

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

7900

RECEIVED
29/1/47
REGISTERED
E F O R A D M I S
TRAFFIC



No. in Reg. Book. **15242** on **25745**

Tonnage Gross **6** Net **3**

No. of Main Boilers **1**

No. of Donkey Boiler Steam Pressure in Main Boilers in Donkey Boilers **1**

Last Report

Particulars

(Periodical Surveys, when if any, and, in detail of which must be stated should be briefly summarised in damage cases where offered his services)

Was a damage report offered by the Surveyor?

Did the Surveyor report that this was not done?

And what parts of the engine were examined?

Also what special measures were taken by the Surveyor to assure State, latest date of examination?

Did the Surveyor examine the boiler?

Did the Surveyor examine the engine parts?

Did the Surveyor examine the insulation?

Has the shaft now been examined?

Has the shaft now been examined?

State date of examination?

Engine parts, when reported to be defective?

Has the insulation been examined?

If the Surveyor is not satisfied with the results of the examination, he should state the reasons therefor.

RECEIVED
29/1/47
REGISTERED
E F O R A D M I S
TRAFFIC

Survey I took of the ship

... of the ship ...

... of the ship ...

... of the ship ...

Referred to Mr. A
Referred to Mr.

... of the ship ...

POS-OPP

General (State clearly to be made)

Regular