

March 1st, 1918.

Plate above  
costal Plate

1500/10/17.

1

Sent to Chief Surveyors 12.4.18

Received from Chief Surveyors

VESSEL'S NAME *Sheela Herbert L. Pratt*

Report

No. 2675

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

❖ 100 A-1 (Steel) Laming petroleum in bulk  
2 Dks (Steel) & Webframes Longitudinal Framing

Cell DB 4E+857 1796. DT. 56' 10386. FPT 976. ART. 746


FK. 15 BH (11 Upper 4 1/2" Dk) pl. asp. A+C.P.

P 122. 6.50' F 42' Mchly abl

*Prelim. pass in proof.  
filled in by JAT in  
Revis 13.5.18*

(Signed) S. BLACKETT.

or Surveyor to Lloyd's Register



© 2020

Lloyd's Register  
Foundation

W992-0243

nger Plate,  
th & thickness  
No.

ide Hatchways

*See page*

3" x 14"  
2  
2 1/2" x 16"  
4  
15  
25  
40