

No. of Bilge pumps 2 Diameter of ditto 65 Stroke 480 Can one be overhauled while the other is at work Yes

TELEPHONE No. 11-65.

Lloyd's Register of Shipping,

47, Quai de la Fossé,

Nantes, 9th February 1922



LLOYD'S REGISTER.
LONDON
11 FEB 1922

RECE
ANS?

G. G. DEMAREST,
G. A. LAING,
SURVEYORS.

Reference

E.

THE SECRETARY

71, Fenchurch Street, 71

LONDON. E.C.3.

Sir ,

In reply to your letter of the 7th instant regarding 1st Entry Report N° 1256 on the machinery of the S/S/ "CAPITAINE WINCKLER" I beg to state the spare sets of feed and bilge pump valves are not yet onboard, nor is the spare gear of this vessel otherwise complete, attention to which was drawn in my accompanying letter of the 2nd instant.

I am , Sir ,

Your obedient servant,



© 2020

Lloyd's Register
Foundation

W993A-0116

W993A-0117

al of flue plates

THE SURVEYORS ARE REQUESTED TO WRITE ACROSS THIS MARK

ested and nt.

and

to bot
'er
n Eng
m bul
r belo
got an
d
es
He
t and
ra
ably
le
of Co
nd De
he
they
5 Ma
riveti
idth
in sh
Steer
No. of
5
Work
13k.
4/5
ront
ressur
M
Ma
stay
be sh
tudine

Referred to the Chief Engineer Surveyor

RAM

11 FEB 1922

L.H.
13/2/22



© 2020

Lloyd's Register
Foundation

No. of E

RGIN