

Did the Surveyor examine the vessel prior to Master taking

ds adjusted un

Kerwegian.

HFX3352
11/1 1948

A furnace & the air pump
repaired.

It is submitted that
this vessel is eligible to
remain as CLASSED.

P/I due 4-40.



2020
20/3/41

Lloyd's Register
Foundation

W9934-0140