

15

## Port

Belfast

I have to report that the undermentioned Iron or Steel Forgings or  
strings, manufactured by Messrs Sunderland Forge & Eng Co<sup>ltd</sup>  
Sunderland for the Vessel No. 445, being built  
Workman Clark & Coy<sup>ltd</sup> of Belfast  
have been inspected by me as set forth below and found to be, so far as can  
seen, Sound

~~gings or Castings.~~

שנ'ס

D. D. Williamson

Sunderland. 23-10-19

Lower Part of

	STERN FRAME.	RUDDER FRAME.	STEM.
...		Scrap Iron	
...		Forged	
...		10" dia - 6 1/2" dia	
Inspection ...		Forged & Finished	
Inspected }		24-9-19 to 26-9-19	
TINGS.			
Standard Test			
pieces.		was not <u>stamped</u> .	
...			
square inch			
...			
per cent. ...			
g Test-			
e fracture			
...			
ground ...			
Test-			
according to Rules			
satisfactory ... }			

KETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

The Rudder Stock has been inspected by me at the Shipyard and found to be so far as can be seen, sound.

J. M. Huema

Belfast. 21/10/19

24 OCT REC

any chargeable) £

be paid at

, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

W993A-0216

Toe Bulb, or Channel.....)

Angle on ditto