

List of Work to complete 1st Entry Report.

3m.1.15.

Received by Chief Ship Surveyor 11-6-15.

Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel S.S. "GLENIFFER" Rpt. No. ....

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry

It is submitted before this case receives the consideration of the Committee this report should be handed to the London Surveyors for their information and guidance in dealing with the case.

O.K.  
11/6/15

*[Signature]*

11-6-15.

77969

RECEIVED



© 2020

Lloyd's Register Foundation

W9938-0033 1/2 STEEL

Inches in Ship	Inches Spacing in Ship	Inches in S
7	3 1/2	5
4	4	4
2	42	74
	72	
	6.6	
	50+	
	72	40.5
	4.4	5
	45	
	4.4	
	40	
	3 1/2	3 1/2
	5 x 3 1/2	P

Deck	Material and thickness	WEATHING
Bridge Deck	Stringer Plate, holdth & thickness	7/16