

11 DEC 1940

to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME KING IDWAL Report LIV No. 115215For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Description of Survey DAMAGE When due.....

Subject to indented shell plating in the 3<sup>rd</sup>, 4<sup>th</sup> + 5<sup>th</sup> staves below sheer (S.S.) abreast after end of N<sup>o</sup>.1 hatch being dealt with at the Owners' convenience.

WAL  
11.12.40



© 2020

Lloyd's Register  
Foundation  
W9938-0233