

5
WS 522
15th April, 1943.

The Principal Surveyor

New York.

S.S. "MARKAY"
Phl. Rpt. No. 8299

Dear Sir:

We are in receipt of your letter of the 14th inst., regarding the above report, and have to state as follows:-

The Requirements of Section 20 of the Rules have been complied with and the breadth of 8" for the through brackets at the oiltight bulkheads on Side Longitudinals Nos. 1 to 5, was approved and that the Scantlings of the side transverses in the bridge tween decks are as in sister ships.

The length of the erections in accordance with Circular No. 1551 are as follows:-

Poop 104.5' - Bridge 36' - Forecastle 55.2'

Yours very truly,

SSM



© 2020

Lloyd's Register
Foundation