

Less Crew Spo  
Less above  
Engi  
TONN

COPY FOR LONDON OFFICE ✓

12.67

Residence 17 Battery  
Part belonging to New

MS: REGISTER, BOSTON.

TELEPHONE 3021 MAIN.

AIN.

**LLOYD'S REGISTER OF SHIPPING,**  
89, STATE STREET,

**BOSTON. 1st September, 1917.**

LLOYD'S REGISTER  
NEW YORK  
REC'D SEP 4 1917

ANS'D \_\_\_\_\_

The Secretary,  
New York.

*S. Heck*  
*Ans*

*send for 6/9/17.*

Dear Sir:-

With reference to your letter of the 29th ultimo, regarding Report No. 924 on the Steamer ' PENNSYLVANIA ', I beg to inform you that the thickness of the second deck plating is .4", and regret that this was omitted in the report.

Yours faithfully,  
*John S. Heck.*



© 2020

Lloyd's Register  
Foundation

w996-0164

w996-0167

certificate issued by the Society of the Surveyors, or other  
indigent, default, or negligence of the Surveyors, or other

anger Plate, br'dth & thickness

ditto.....

54  
3 1/2 x 3

BEAM