

summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the

# POSTPONED SURVEYS.

Case of the..... S.S. "AMERICAN ARROW".

No. <sup>61500</sup> ~~10209~~ in Reg. Bk..... tons, Built.....

Classed..... Owners.....

Port of Registry.....

Survey Due..... General Examination due 11.45.  
Boiler Survey due 10.45.  
Screwshaft Survey due 6.46.

Action in this case was deferred in November last in view of the fact that the vessel was operated by the U.S. Navy.

It was noted from the Shipping Papers recently that the vessel had been returned to the War Shipping Administration and in reply to enquiry the New York Surveyors state the vessel is now laid up in the Mobile River.

? Undertaking,

*Submitted action be deferred*  
*24/7/46* *Beck*

FRI. 5 JUL 1946

Committee's Minute.....

Decision.....

*Deferred undertaking*  
*M*

*Lloyd's 5.7.46*

6c.11.45.



© 2020

Lloyd's Register Foundation

W997-0179

W997-0182