

ter boss

✓

If the liner is in more than one length are the junctions made by fusion through the whole thickness of the line

Nos. *2065-14*  
*208754* Made by *Rustin & Hornsby Ltd.*


*Cas. Muias Galrie No. 112.*

*Nottingham* Report No. *25*  
" " " *C. 647*

It is submitted that a copy of this Report be  
forwarded ~~returned~~ to the *Lisbon* Surveyors for their  
guidance and for completion.

*Copies being  
made  
sent 14/5*

Date



© 2020

Lloyd's Register  
Foundation

Sea Connections fitted direct on the skin of the ship

Are they fitted with Valves or Cocks

Are the Overboard Discharges above or below the