

the internal surfaces of the receivers be examined

What means are provided for cleaning their inner surfaces

here a drain arrangement fitted at the lowest part of each receiver

In Pressure Air Receivers No.

Cubic capacity of each

Internal diameter

Thickness

Russell & Company Ltd.

Engines Nos. 3629, 3630, 3641, 3642

Mech. Reports Nos. 10666, 10667, 10759, 10775-
for Loch Ferting Co. Ltd.

It is submitted to Lisbon Carriers
be requested to state if these engines
have yet been fitted into any of the
vessels already built.

It is noted that Russell & Company
have also made auxiliary engines for these
vessels.

Ans Mr Lis
28/8



© 2020

25/8/20

25/8/20

25/8/20

Lloyd's Register
Foundation