

S.S. "British Merchant"

Gls. Rpt No. 42289

It is submitted the Glasgow Surveyors be requested to state whether the screw shaft of this vessel, examined by them on 23/2/22, runs in oil and is fitted with an approved oil gland at its after end.

The Surveyors should be informed that in all future cases when reporting surveys on vessels whose screw shafts run in oil and are fitted with approved glands, or other approved appliances, the type of gland should be stated on the report.

Lr Gls 14/11/22

C.A.B. 9/11/22 Lloyd's Register Foundation

length of plain part bottom ✓ Thickness of plates bottom 7/16 Description of longitudinal joint Welded No. of s Working pressure of furnace by the rules 213 Combustion chamber plates: Material steel Thickness: Sides 4/16 Back 11/16

in ho  
2"  
2) 6"  
d in Engin  
yes  
r below the  
origo and b  
Partch  
angle  
of Certifi  
No. and 1  
Are they f  
Mate  
of riveting  
es or width  
in shell  
stud