

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Wood Schooner "K T"*

Report *Arklow No. 665^d*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey *1st entry.*

The stream chain supplied to this vessel is 3 lbs. less in weight than required by Table 22 for the same size and length, but it is 1/16" larger in diameter than required by Table 22 for this vessel. In other respects she

This vessel appears to have been built in accordance with the Rules and the approved sketch of midship section, and it is submitted she is eligible to be classed 12A1 with the notation "Keelson pitch pine"

*as follows :- 10 years ^{per} Table A.
1 year mixed material Sec.34 par.11.
1 year for salting per Sec.37 paras.3-7.
12A1 "10 & 12 years material. Salted Keelson pitch pine"*

1DK. Lloyds A&CP. CIB

*J.H.T.
9/5/00*

The stream chain is 3 lbs less in weight than required by Table 22 for same length & size, but is 1/16" larger in diameter than required by Table 22 for this vessel.

*J.H.T.
18/5/00*



© 2021

Lloyd's Register Foundation

WEY10 31-0262