

5m,7,30.

8 AUG 1930

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel Bk. "OLIVEBANK". Rpt. Mel. No. 4727

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

Nature of Survey .....

The Melbourne Surveyors report that temporary repairs have been effected to a defective shell plate etc. on the starboard side. *AFT*

The Surveyors recommend that permanent repairs be carried out on vessel's arrival at a home port.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

*As now: Subject etc.*

~~PLATING to be DRILLED~~  
~~at next Special Survey~~



© 2021  
*William*  
7.8.30.  
Lloyd's Register  
Foundation