

12 SEP 1932 4

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *Stl 4 mast B<sup>16</sup> " OLIVEBANK* Rpt. *Lon.* No. *97894*,

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey COMPLETION OF H<sup>1</sup> S.S. No. 1

The H<sup>1</sup> S.S. No. *1* partly held at *Opn.* H<sup>1</sup>S  
now completed, and the following repairs done (due to *wear & tear*) :-

- Vessel placed in dry dock, bottom cleaned & coated.
- 3 stem plates renewed and minor repairs effected.

It is submitted the vessel is worthy to remain as classed, with record of Survey *9.32* and notation of *S.S. H<sup>1</sup>S No 1-31* as recommended.

*100A.1.*  
*9.32 Lon*  
*S.S. H<sup>1</sup>S No 1-31*

~~PLATING to be DRILLED~~

*12 years from 10.31*



© 2021 Lloyd's Register Foundation  
*9.32*  
*9.9.32*  
*986*