SHEET Nº 1.



Note. No access to For^wd Bulk^hd
Nº 5 Centre Tank.
No 4 Flooded Preventing
access to Hº 5 Port Wing Tank
For^wd Bulk^hd

GIRTH READINGS Nº 5 TANK.
S.S. "CALTEX LIVERPOOL"

Figures in red indicate check drillings.

SURVEYOR TO LLOYD'S REGISTER
SYDNEY, N.S.W.

U/S READINGS BY
DOUGLAS BELL ASSOCIATES
PER Douglas Bell
9.4.67.

© 2020 Lloyd's Register Foundation