

Received by Chief Surveyors 22-11-97

Received from Chief Surveyors

5

No. 2 SURVEY PARTLY HELD.

VESSEL'S NAME *Im 88 Strathleven* Report *Barry* No. 2736

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

When proposed to be completed

Portion of Survey held, &c.

The S.S. No. 2 due 10.97 has now been partly held as

follows:- Bottom examined in dock

The Hong Kong Surveyor recommended in March 1896 a shoe plate on after ~~heel~~, the Barry surveyors now state that in their opinion no repair of any kind is necessary and the following repairs done (due to wear & tear):-

Rudder bushed & steering gear overhauled & general deck overhauled. A new wire & manilla hawser supplied

~~It is proposed to complete the survey~~

It is submitted this ~~proposal merits approval and~~ the vessel is worthy to remain as classed, record of Survey 11.97 and notation of S.S. No. 2 being deferred until completion of same.

act

22-11-97

The following remains to be done to complete the S.S. No. 2

viz:- All the rule requirements except the docking



© 2018

Lloyd's Register
Foundation