

Date of writing Report 7th July 1943 When handed in at Local Office 7th July 1943 Port of Grimsby
No. in Survey held at Grimsby Date, First Survey 18th May Last Survey 5th July 1943
Dog Book (No. of Visits) 34

No. in *Survey held at* *Trinity* *Date, First Survey* *18th May* *Last Survey* *5th July* 19*18*
 Reg. Book *(No. of Visits)* *34*

~~Lizzie~~ on the Wood, Iron or Steel LIZZIE & ANNIE

TONNAGE:-	By whom	When	YEAR.	MONTH.
10527	C. H. Shields	I. S. S. & Sons	1844	6

114
 GROSS
 114

OWNERS B. N. Clements, Big Lagoon Co, Ark. OWNERS' ADDRESS (if not already recorded in Appendix to Register Book).

Managers ✓ Port belonging to Hull.

Surveyed Afloat or in Dry Dock? Subway Name of Dock _____ Destined Voyage _____

Cell DBor DBa	feet; uE&B	feet; f	feet	Particulars of Classification (which must be inserted <u>precisely</u> as in Register Book & Supplements)
total capacity	tons. FPT	tons; APT	tons; MT	

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 51659	Port Hul.	+ 90A1	LMC-438
------------------------	-----------	--------	---------

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated), should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom? *Yes Underwriters*

REPAIRS, OR EXAMINATION AS PER RULE, FOR S. S. 5-Hy. 2 & Damage.

Vessel placed on slipway, bottom & rudder cleaned, examined & recoated. The holds fore & after peaks, forecabin, chain locker, machinery space & cabin cleaned, examined & recoated as necessary. All close ceiling in No. 1 & 2 holds removed, & the plating, framing & all iron work cleaned, examined, & recoated. The decks, mast (wedges removed), rigging, ventilators & coamings, casings, hatchways, hatches & supports & battering down arrangements, general equipment, steering gear & connections, windlass, hand pumps & air & sounding pipes examined.

Frederick verified & new certificate issued.

Damage, stated due to vessel grounding in River Welland near Boston on the 11th May, 1943, whilst on a voyage from Tardifke to Grimsby.
Vessel raised on slipway, bottom & keel examined. Keel lifted & examined. Port chain cable, raised & examined. P.T.O.

SUMMARY OF DAMAGE REPAIRS:--	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:--
Renewed	13	13	28	13	✓	✓	✓	<i>Per report.</i>
Removed and Faired or Repaired	1	✓	✓	✓	✓	✓	✓	
Faired or Repaired in place	6	4	✓	✓	✓	✓	✓	

[illegible]

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 138," or "to remain as classed and to have record of survey, 138, and the notations of ss No. 1-38."

This tract is now in efficient condition and eligible in my opinion to remain as classed with fresh record of survey 7-43 and notation of D. S. Sur. No 2-43.

Survey Fee (per Section 20) 154.92 4 : 10 : 0 Fees applied for,

Special Damage ~~or~~ Repair Fee (if any).....£ 15 : 15 : 0

Travelling Expenses (if chargeable) £ 1 : 2 : 2

Contractor's Fee (if any) 1000

Second Surveyors Rec (11 Aug)

Committee's Minyte

943

Character Assigned

~~Wm. C. C.~~ 2.2. 1908 100-40. (1)

White Pine Co. 2, 3, 42.

Fees applied for,

7. 7. 1943

Received by me,

19

1000

1943

1

9-48 (2)

天-425

1

Surveyorsto Lloyd's Register of Shipping.

