

to Chief Surveyor

Received from Chief Surveyor

SEL'S NAME

12 3 97

S.S. Baku Standard Report Rec No. 34530

For the ~~CHIEF SURVEYOR~~ **CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

When due

It is submitted that the Superintendent states that although some of the fittings are still on board, liquid fuel is not now being used in the furnaces of the boilers, the notation "Burning liquid fuel experimental" should therefore be expunged from the Reg. Book.

[Signature]
12.3.97



© 2018

Lloyd's Register
Foundation