

MON. 25 JUL 1898

(Received at London Office)

Please affix  
No. 3.

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report July 11th 1898 When handed in at Local Office

is Port of Batoum

No. in Reg. Book. Survey held at Batoum on the Wood, Iron or Steel

Date, First Survey 11th July Last Survey

1898

30 29 TONNAGE: 3708 British 11. " Lake Standard" No. of Visits Master Mr. Kerr

ISS 3335 Built at Liverpool or Lyre. By whom Armstrong, Mitchell &amp; Co

DER DK 2345 Owners Impair Petroleum Co. Ltd

ET 2345 Owners' Address Dock road, Millers Avenue London E.

Surveyed Afloat or in Dry Dock? Afloat Name of Dock

T.D.-DBa tons; f tons; uE&amp;B 139 tons; CellDB

tons; tons;

FPT 187 tons; APT tons; MT

N.B.—All alterations in the existing records should be underlined.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER:

for special survey,  
Date of last Survey and of  
Periodical Surveys.

+100 At 1 Share dt. + LMC.

1097 Carrying petro. 3.97

6.98 in bulk

S. S. No. 1 - 97

Society's Freeboard (if assigned) as  
painted on Ship and now verified

6' n. 5" in.

Survey, No. 36796 Port Mwe

1. Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; items being detailed in the body of the report, should be summarised in the form shown below. Whenever the weight of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles is clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment if any. State also the dates and initials of any letters respecting this case.

IS, OR EXAMINATION AS PER RULE, FOR Sect. 28 6 6

Damaged sustained through collision with up "Rock light" of liner pool on starboard side of ship and just fore part of bridge, opposite oil tank No. 5 following damage:-

Below deck stanchion bent, 1 ditto broken; top rail bent in board & broken.  
Deck- Deck expansion strained & rivets started, - gangway rails bent in, 1 Balustrade plate bent in & one ditto cracked & bented.-

In Deck. - 4 Plates bent, several rivets started, 6 frames bent & strained  
1 several rivet bent jumped off.-

Oil tank. - 3 plates bent, and 1 few rivets slightly started & 2 frames slightly bent.  
Starboard side. - in way of main rigging the eye bolt of accommodation ladder  
is warped and flat on which eye bolt is riveted is bented in board.

BY OF DAMAGE REPAIRS:— Plates, Fair'd or Repaired:— Frames, ditto:— Plates, Renewed:— Frames, ditto:— Other Repairs

CONDITION OF THE

Transoms, Pointers, & Crutches	Copper, or Y.M. (State if on Felt.)	Hatches
Timbers of Frame at the openings	When put on, Month	Boats
Ditto ditto at other places	Year	Masts, Yards, &c.
Keelsons	Rudder	Condition, how ascertained
Clamps, Shelves & Stringers	Windlass & Capstan	Sails
Salting (State if examined.)	Pumps	Equipment letter
Ceiling	Engine Room Skylights	Anchors, No. of
Cement (State which.)	Coal Bunker, Open'g, Lids, &c.	Cables (State if now ranged)
Tanks (State if now tested.)	Scuppers	.. length size
Caulking of Bot'm, Dk, & Wat'rwy's	Cargo & Main Hatch'ys	.. Rule length size

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon his survey, thus, for example:—"..... to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9.91," or "to remain as classed and to have record of survey, 9.91, and the notations of as No. 1-21 and 1-21, &c."

130 During the examination the shore damage does not affect the seaworthiness of the ship and in view of the fact that she has to load a cargo for Manchester direct I have recommended that she should be loaded on the first opportunity. I have granted a certificate of seaworthiness.

Fee Fee (if chargeable) per Scale II., Sec. 22 £ : 10 :

Fees applied for,

Survey Fee (per Section 28) £ : : :

18.

Special Damage or Repair Fee (if any) £ 2 : 2 :

Received by me,

Travelling Expenses (if chargeable) £ : : :

18.

Second Surveyor's Fee (if any) £ : : :

A Certificate now required? £ 2 : 2 :

Committee's Minute TUES. 26 JUL 1898

Character assigned Deferred for

Written over. further notice.

Rept. to India 27/7/98

5.8.98

FRI. 12 AUG 1898

FRI. 23 SEP 1898

© 2018

FRI. 14 OCT 1898

Lloyd's Register

Foundation

