

by Chief Ship Surveyor 6/3/11.

Received from Chief Ship Surveyor _____

EL'S NAME Stl. S.S. "Baku Standard" Rpt. Nwc. No. 59875.

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/03.)

of Survey _____

Completion of 2nd S.S. No. 1.

It is submitted that, before this case receives the consideration of the Committee, it should be pointed out to the Newcastle Surveyors that the Rules require each oil compartment and coffer dam to be tested at special Surveys by being filled with water to the top of the hatchway in the expansion trunk, and they should be requested to state why only alternate tanks were filled in this case. ~~and why he recommended the need for record of S.S. No. 1 without the whole of the tanks being tested.~~

Classing th. to Nwc.:-

R.A.
M.
E. L. L.