

11

1961 NOV 22

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME S/S Hms B<sup>k</sup> PAMIR. Rpt. Hamb. No. 20167.**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02).

Nature of Survey \_\_\_\_\_

The Hamburg Surveyors report this vessel placed in dry dock, bottom cleaned and coated. ~~and minor repairs effected.~~

It is submitted the vessel appears worthy to remain as classed with record of survey 11.31 as recommended.

100 A. 1.  
11.31 Hamb

PLATING to be DRILLED when  
vessel is 24 years old  
or at next survey



23.11.31



© 2018

Lloyd's Register  
Foundation