

24 JUL 1952/

"PAMIR"

Rot.34988

Before this case receives consideration, IT IS SUBMITTED the Dusseldorf Surveyors be informed that a bronze propeller bearing the following marks has been fitted to the above vessel:

LLOYDS No.P2 15-16. 8488. K.M. 29-5-52

The Rotterdam Surveyors state they have been informed by the Dusseldorf Surveyors that "the dimensions of this new propeller are insufficient for this main engine".

Please forward a copy of the certificate covering this propeller, together with comments regarding the insufficient dimensions.

Euk

23. 7. 52.



© 2018

Lloyd's Register
Foundation