

23 JUL 1958

(E) m n e 3



Reference :
Class (S)
29 AUG

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Hamburg 1, Ballindamm 25

Telephone: No. 37 10 22

27th August, 1926

Telegrams: Surveyor, Hamburg

Dear Sir,

"PANTIN" - Hamburg Bot. No. 4893

With reference to the query contained in your
pleasing letter dated 21st August as to why all the chain
cable was tested, we have to advise you that this was
carried out purely at the request of the Master.

The testing of this cable was queried by both
Germanischer Lloyd Surveyor and the Society's Surveyor
attendance on the job at the time, but the Master stated
he wished to have on board a clean set of test certificates
for his chain cable, and therefore desired the cable to be
re-tested, in order to regularise his certificates.

Yours faithfully

The Surveyor

For:-

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

W. J. C. C. C.

Noted 30.8.26 J.P.R.

[Signature]

W. J. C. C. C.

CLASSIFICATION

23/25

4



© 2018

Lloyd's Register
Foundation

LR-FAF-5A23-428