

# Report of Survey for Repairs of Engines and Boilers.

No. 3111 (Received at London Office, )  
 No. in Reg. Book. 974 Survey held at Goole Date, first Survey 2<sup>nd</sup> Sept. Last Survey 13<sup>th</sup> Sept. 1881.  
 on the Machinery of the Stul screw Steamer 'Annie' (Number of Visits 3)  
 Tonnage, Gross 443 Built at Hull When built 1864  
 Ditto, Net 274 Owners Goole Steamship Co. (Ld) Port belonging to Goole  
 Diameter of Cylinder 21 30 1/4 Engines made by M. Samuelsen When made 1870  
 Length of Stroke 24 Boilers made by D. When made 1874  
 Pressure of Steam 60 lbs If Surveyed Afloat or in Dry Dock Afloat & in dry dock Classified A-  
 Registered Horse Power 98 (State name of Dock.) Lloyds & Co. Ltd 1. 17  
 Last Survey No. Port S. S. Gov. No 2. 51

Particulars of Repairs and Examination of Crank Shaft & Bilge Injection in continuation of Survey of December '80. - (see Hull machinery report No 193) and in accordance with Committee's minute of 11<sup>th</sup> Jan. '81.

A new half crank shaft has been fitted to the forward Engine. also a non-return valve for the bilge injection in connection with circulating pump. Propeller. outer end of Tail shaft & stem Bush. also fastenings of Sea Connections examined in dry dock. found in good order.

General Observations, Opinion, and Recommendation:— This case is respectfully submitted as eligible to remain as classed.

Entry or Registering Fee... £ " : " : "  
 Survey Fee (per Section 28) ... £ 1 : 1 : " received by me, MMZ  
 Certificate (if required) ... £ " : " : " 24/9/1881  
 to be sent as per margin.  
 Travelling Expenses, if any, £ 0 10 6

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, September, 27<sup>th</sup> 1881.

Assigned

Noto the withdrawal of this  
of this



© 2018  
 Lloyd's Register  
 Foundation



