

COPY.

# Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.

31st July, 1917.

Dear Sirs,

With reference to the classification in the Society's Register Book of your S.S. "STETTIN", I beg to acquaint you that the Committee have had before them a report received from the Society's Surveyors at Newcastle of an examination made of the vessel afloat. They report that damage has been sustained to the stem, stemplating, frames &c., through striking a quay wall, and that temporary repairs have been effected to their satisfaction to enable her to proceed on her voyage.

It is recommended that permanent repairs should be carried out on the vessel's return from her present voyage, and the Committee have accordingly continued the vessel's class subject to this being done.

I take this opportunity to remind you that the annual survey of the boilers is now due.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. James Currie & Co.,  
16, Bernard Street,  
LONDON.



© 2018

Lloyd's Register  
Foundation