

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

20 NOV 1918

VESSEL'S NAME Iron S.S. "STETTIN".

Rpt.

Nwc.

Nº 1400

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the nature or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 1914/15.)

Nature of Survey

The Newcastle Surveyors report this vessel has been examined in dry dock, a few shell rivets renewed, and minor repairs carried out and the bottom cleaned and coated.

Three lengths of shoe plate at the forefoot are much worn, and the Surveyors recommend these be renewed at the next dry docking.

It is submitted the vessel appears worthy to remain as classed with record of survey 10.18, subject as above and as recommended.

A-1.
10.18 Shl } Subjective



© 2018

Lloyd's Register
Foundation