

2-JUL-1920

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Iron S.S. "STETTIN". Rpt. Lth. No. 5769

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/3/92.)

Nature of Survey \_\_\_\_\_

The Leith Surveyors report this vessel has been placed in dry dock, the bottom and rudder cleaned and coated and the 5th. S.S.No.1, due 6.19, carried out.

On account of wear and tear, the rudder has been lifted and pintles rebushed as required, frames and reverse frames repaired as required, deck and tunnel plating renewed as necessary, and sundry minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.20 and notation of S.S.Lth.No.1-20.

A.1.

6.20 Lth.

S.S.Lth.No.1-20.



© 2018

Lloyd's Register  
Foundation