

2nd January 1890.

Dear Sir,

With reference to the classification
this Society's Register Book of you & S.
the Council, I have to acquaint you
3/11 that it appears from a report received
from the Society's Engineer Surgeon at Genoa,
that the tail shaft of this vessel is
somewhat slack in the lignum vitae, and
the latter should be removed when
vessel is next placed in dry dock,
I shall be glad if you will kindly
give me timely notice, when and where,
will next dock the vessel.

I am,

Dear Sir,

Yours faithfully,

Wm. H. Murray
Asst Secretary

Wm. H. Murray
Asst Secretary