

Translation of letter dated the 10th March from
NORDEUTSCHER LLOYD BREMEN

Reference: M.S. "BERLIN", Classification of
Refrigerated Cargo Installation

Dear Sirs,

Since the M.S. "BERLIN" ex "GRIPSHOLM" was transferred to our fleet we have not had occasion to use the refrigerating machinery as the required minimum temperature of minus 6°C by the freighters. For this reason we do not wish to maintain the classification of the refrigerating installation of this ship and we shall, therefore, be glad if you will kindly expunge this vessel's RMC class in your Register.

Yours faithfully,



© 2018

Lloyd's Register
Foundation