

COPY

## LLOYD'S REGISTER OF SHIPPING

Amended

66/8002

Port B r e m e nDate 22nd March, 1966

**This is to Certify** *that I have surveyed part of the machinery*

*of the* **M/V "BERLIN"** **18 600** *gross tons* **of Bremen**

*for* **Continuous Survey of Machinery whilst she lay afloat at Bremerhaven on the 17th December, 1965 and subsequently to the 4th February, 1966**

*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* **CSM (with date) upon completion DBS 2.66**  
*subject to any outstanding condition of class being dealt with as previously recommended.*

Parts now examined:—

Port M.E. Nos. 1,2,3,4,5 and 6 cyl. covers, pistons, rods, valves and valve gears

Port M.E. Nos. 7 and 8 journals and bearings

Port M.E. thrust block, shaft and bearings

Stb. M.E. Nos. 2 and 6 crankpins and bearings

Stb. M.E. Nos. 4,5,6 and 7 journals and bearings

Port and stb. M.E. tested working and manoeuvring

AUXILIARIES

Port fwd and port aft bilge pumps

Stb. aft fuel oil transfer pump

Port fuel oil service pump

Stb. outer lub. oil pump

Port oil burning pump

Stb. steering gear pump

Port inboard aux. diesel generator engine

Stb. inner aux. diesel generator engine

Centre aux. diesel generator engine

*Surveyor to Lloyd's Register of Shipping*

(K.H. Fedderwitz)

ABS Auxiliary Boiler Survey  
 CSM Continuous Survey of Machinery  
 DBS Donkey Boiler Survey  
 ES Engine Special Survey

MBS Main Boiler Survey  
 OF Fitted for oil fuel (date) FP above 150° F.  
 SGS Steam Generator Survey  
 SPS Steampipe Survey

TS Tailshaft Survey  
 TS(CL) Tailshaft Survey—Continuous Liner  
 TSN Tailshaft renewed  
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society"



© 2018

Lloyd's Register  
Foundation