

See Gls. Rpt 49321.

- EQUIPMENT -

May 1929

Equipment number now 61064.25.

additional equipment . 15 fathoms  $2\frac{12}{16}$  stud link chain  
now supplied and a bower anchor of  $102 - 1 - 14$   
to replace the original third bower now  
removed. (The approved weight of this  
new anchor is  $101 - 3 - 0$ )

Total chain cable now : 345 fathoms  $2\frac{12}{16}$ .



© 2018

Lloyd's Register  
Foundation



It is proposed to complete the survey

It is submitted this proposal might be approved, and the vessel be  
allowed to remain as classed, record of Survey and notation of S.S.  
No. being deferred until completion of same.

The following remains to be done to complete the S.S. No.  
viz:-



© 2018

Lloyd's Register  
Foundation