

38 SEP 1933 5E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Viceroy of India

Rpt. Len.

No. 99207

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24592.)

Nature of Survey

~~DAMAGE &~~ WEAR AND TEAR.

Starb^d. turbine rotor renewed.

- { SS No. 1 due 3.33.
- { BS. WTB. due 9.33.
- { screw shafts due 3.31.

No arrangements have been made to hold these surveys.

It is submitted the vessel is eligible to remain as classed without fresh

record of Survey

~~as recommended.~~

L. J. L.
V 23/9/33


© 2018

Lloyd's Register
Foundation