

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME

Empire Chieftain

Rpt.

*Lab. No. 17523**Hbl. No. 18429**E.P. 18402**Ren. 67885**Arch. 11,193*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

*2 steam turbines DR geared to
1 sc. shaft:**14HP 1226**NHP. 1226. 1210**12/12/44*

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

*Yes*If fitted with an outside gland of
approved type*No*

The working pressure of the boilers has been increased beyond that originally approved in order that the designed power may be reached.

alteration appeared in endorsement dated 11-11-43.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is

eligible to be classed *+ LMC 10.43**Fitted for oil fuel 10.43, F.P. above 150°F.**2 WTB 490 lb. (Spec. 475 lb.)**DB 105 lb.**L. Y.
8/12/43.*

© 2018

Lloyd's Register
Foundation